

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

CAL. 500 WIN MAG				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	THW 1203A		
JS	12/22/03	De-torque Scope Cross Bolt Screw	Front 20 in Lb Rear 25 in Lb		
BL	12/22/03	Headspace	Min +.002		
BL	12/22/03	Proof	Tight opening Bolt	1	1
BL	12/22/03	Headspace	Min +.002		
JS/BL	12/22/03	Depth Front Take	Low. screw		
BL	12/22/03	Firing Pin Indents	.020 - .019 - .020 Avg. .0196		
JS	12-29-03	Seat/Trigger Engagement	Avg. .0274		
JS	12-29-03	Seat lift	.0152		
SV/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min +.003		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.004		
SW	1/14/04	300 Rd Braze Jack Function Test		200	202
SW/JS	1/15/04	Headspace	Min +.004		
BL	1-16-04	Shoulder function test X20 Rds.	Shot clean	20	222
JS/BL	1-19-04	Inspect & clean	See Inspection Sheet		

Logform

39

ET20118

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-6

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

- ☒ Measure Headspace min+.004
- ☒ Sear Engagement: 1st. .0267 2nd. .026 3rd. .0268 Ave. .0265 spec- .020" to .025" 83
- ☒ Trigger Pull: 1st. 4.966 2nd. 4.841 3rd. 4.763 Ave. 4.857 spec- 4 lb. to 5.5 lb.
- ☒ Check Take-Down Screws and Re-tighten if necessary.
- ☒ Inspect extractor & bolt face area.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop worn, some wear on locking lugs
- ☒ Inspect stock for any signs of cracking or other failure.
- ☒ Other items of note: magazine Box protruding, receiver insert has a defect must be in the model

TLW1303

Remington Confidential

ET20119