

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

CALCULATED WIN RPTS				ROUNDS AT START-0	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection			
JS	12/22/03	De-torque Scope Bolt Screws	Front 35 Rear 30		
BL		Head space	min + .002		
BL		Proof	OK	1	1
BL	12/22/03	Head space	min + .003		
JS/BL	12/22/03	Depth Front Take down Screw hole			
BL	12/23/03	Firing Pin Indents	.021 - .021 - .021 - Aug. 021		
JS	12-29-03	Scan/Trigger Engagement	Arg. 1.0272		
JS	12-29-03	Scan lift	.0178		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min + .004		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min + .004		
Pr. Lr	1/15/04	200 rd JACk Funct. test	magazine box hard to take from magazine well / 7FTE Bolt hard to close	200	202
SW	1-15-04	Head space	Min + .005		
BL	1-16-04	Shoulder fire	OK	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

Q

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-24

TLW #: TLW1303

Date: 01/20/04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min+.004

☒ Sear Engagement: 1st .0282 2nd .0278 3rd .0284

Ave. .0281 spec. .020" to .025"

Res Eng.

☒ Trigger Pull: 1st 4.4772 2nd 5.509 3rd 5.271

Ave. 5.086 spec- 4 lb. to 5.5 lb.

10247

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: locking lugs same wear, bolt stop same wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20154