

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

CAL: 300 WIN MAG				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Distance Scope Cross Bolt Screws	Front 25 Rear 20		
BL		Head space	Min + .002	1	1
BL		Proof	OK		
BL	12/22/03	Head space	Min + .004		
JS/BL	12/22/03	Depth Front Take down	Scout		
BL	12/23/03	Firing Pin Indents	.057 - .020 Avg. .020		
JS	12-29-03	Seal/Trigger Engagement	Avg. .028		
JS	12-29-03	Seal Lift	.0168		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min + .003	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Head space	After proof Min + .004		
Blee	1/15/04	2000 Jack Funct test	Bolt hard to close / magazine Prox hard to take from magazine well	200	202
SW	1-15-04	Head space	Min + .005 (Front Take down & Center screw loose)	20	222
BL	1-16-04	Shoulder Fire	Bolt hard to close		
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

CL

Confidential - Subject to Protective Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-25

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min + .004

☒ Sear Engagement: 1st .0273 2nd .0258 3rd .0268

Ave. .0266 spec. .020" to .025"

83

☒ Trigger Pull: 1st 4.082 2nd 4.193 3rd 4.187

Ave. 4.154 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop worn some

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20156