

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Measure - Scope Crosshair	Front 40 Rear 40		
BL	12-22-03	Headspace	min +.003	1	1
BL	12-22-03	Proof	OK		
BL	12-22-03	Headspace	min +.003		
JS/BL	12-22-03	Depth Front Take down	Scope hole		
BL	12-28-03	Firing Pin Indents	.018 .019 .019 Avg. .0186		
TS	12-29-03	Seal/Trigger Engagement	Avg. .0298		
JS	12-29-03	Seal IFI	.0154		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Headspace	Min +.004	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Headspace after proof	Min +.004		
SW	1/15/04	200 Rd Basic Jack Function Test		200	202
SW	1-15-04	Headspace Min +.004	(Center Take down screw loose)	20	222
BL	1-16-04	Shoulder Fire	ok		
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

6

ET20162

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-30

TLW #: TLW1303

Date: 01 / 20 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace max .004

☒ Sear Engagement: 1st. 0.292 2nd. 0.279 3rd. 0.277

Ave. 0.282 spec- .020" to .025"

☒ Trigger Pull: 1st. 4.801 2nd. 4.858 3rd. 4.733

Ave. 4.791 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Some wear on bolt face

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear, Bolt stop worn

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20163