

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

[illegible]

Logform

— 1 —

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A72

TLW #: TLW1303

Date: 3 / 8 / 04

Inspector: BL

Round Level: 701

- ☒ Measure Headspace min+.000
- ☒ Inspect Take Down Screws for loosening. no movement
- ☒ Sear Engagement: 1st. .0302 2nd. .0297 3rd. .0301 Ave. .02996 spec. .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 4.450 2nd. 4.218 3rd. 4.769 Ave. 4.279 spec- 4.5 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 4.685 2nd. 4.834 3rd. 4.934 Ave. 4.804
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs some sign of wear
- ☒ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole

☐ Other items of

note:

TLW1216

Remington Confidential

ET21091