

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL AND PILOT TEST 1.1

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .004		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .004		
SW/JW/BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
BL	2/19/04	200Rd Jack Funct.		200	201
JS	2/24/04	500Rd Ext. Endur Test		500	501
BL	3/9/04	Clean/Inspection	See Inspection Sheet		

Logform

Q

ET21104

Confidential - Subject to Protective Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-19

TLW #: TLW1303

Date: 3 1 9 1 0 4

Inspector: BC

Round Level: 701

☒ Measure Headspace min .004

☒ Inspect Take Down Screws for loosening. Top screw 1/2 turn - Center screw 1/8 turn 83

☒ Sear Engagement: 1st. .0323 2nd. .0317 3rd. .0311 Ave. .0317 spec. .025" to .030"

☒ Reset Sear Engagement if Required: 1st. .0282 2nd. .0293 3rd. .0289 Ave. .0288

☒ Trigger Pull: 1st. 4.558 2nd. 4.746 3rd. 4.923 Ave. 4.743 spec- 4.5 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs some sign of wear

☒ Inspect stock for any signs of cracking or other failure: cracked stock at center screw hole

☐ Other items of note:

TLW1216

Remington Confidential

ET21105