

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

CALC. 500 FORM 1				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .003		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .003		
SW / JW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd JACK funct.		200	201
BL / JW	3/1/04	500 Rd EXT. Endur Test		500	701
BL / JS	3/2/04	Clean / Inspection	see Inspection sheet		
BL	3/3/04	1000 Rd EXT. Endur Test		500	1201
BL	3/3/04	Clean / Inspection	see Inspection sheet		
PKR	3/4/04	Attempt to Torque Front Take-Down screw to 85 In. Lbs.			
		Screw Hole in receiver stripped out.			

Logform

4

ET21122

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-28

TLW #: TLW1303

Date: 3 12 04

Inspector: J. Sims/Blee

Round Level: 701

- ☒ Measure Headspace min+.004
- ☒ Inspect Take Down Screws for loosening. Front Take down screw loosened 1/4 turn.
- ☒ Sear Engagement: 1st. 0.296 2nd. 0.291 3rd. 0.287 Ave. _____ spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 3.769 2nd. 3.733 3rd. 3.645 Ave. 3.716 spec- 4.5 lb. to 5.5 lb.
- ☒ Reset Trigger Pull if Required: 1st. 4.899 2nd. 4.961 3rd. 5.158 Ave. 5.006
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, locking lugs, bolt stop show some wear.
- ☒ Inspect stock for any signs of cracking or other failure: stock cracked at the center take down screw

☐ Other items of

note: _____

TLW1216

Remington Confidential

ET21123

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-28

TLW #: TLW1303

Date: 03 / 03 / 04

Inspector: BL

Round Level: 1001

- ☒ Measure Headspace min+.004
- ☒ Inspect Take Down Screws for loosening. Top screw to Turn - Center 44 Turn
- ☒ Sear Engagement: 1st. .0289 2nd. .0297 3rd. .0289 Ave. .02916 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 4.726 2nd. 4.532 3rd. 4.399 Ave. 4.552 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, Locking Lugs, Bolt stop some wear but not excessive
- ☒ Inspect stock for any signs of cracking or other failure: stock cracked at the center take down screw hole
- ☒ Other items of note: used Loctite 222MS on Top and Center take down screws.

TLW1216

Remington Confidential

ET21124