

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detonate Scope	Front 20 Rear 15		
BL	12-22-03	Headspace	min +.006		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min +.006		
JS/BL	12-22-03	Depth Front Take down	Screws hole		
BL	12-23-03	Firing Pin Indent	.020 - .020 - .021 Avg .0203		
JS	12-29-03	Coll/Tripping Engagement	Arg. .0274		
JS	12-29-03	Seal lift	.0155		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.007			
SW/JS	1/13/04	Proof & Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.007		
JS	1-15-04	200 Rd Jack Function Test	Bolt hard to close on Rds 61-80; 121-140	200	202
SW	1-15-04	Headspace Min +.007	Front & Rear Take down screws were loose)		
BL	1-16-04	Shoulder Fine	Bolt hard to close	20	227
JS/BL	1-20-04	Inspect & Clean	See Inspection sheet - Broken extractor		

Logform

Q

ET21308

Confidential - Subject to Protective Order

Williams v. Remington