

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/BR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detorque - Scope Crossbolt Screws	Front 25 Rear 25		
BL	12-22-03	Headspace	min + .005		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min + .005		
JS/BL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Fitting Pin Indents	.015 - .019 Avg .019		
JS	12-29-03	Gear/Trigger Engagement	Avg. .0281		
JS	12-29-03	Gear lift	.0112		
SW/JS	1/13/04	Change out Bolt Head			
SW/JS	1/13/04	Headspace Min + .007			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof Min + .007			
JS	1-15-04	200 Rd. Jack Function test	Bolt difficult to close on. Rds. 81-100; 121-140	200	201
SW	1-15-04	Headspace Min + .007	(Front Take down screw was loose, Center was loose)		
BL	1-16-04	Shoulder Fine	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

3

Williams v. Remington