

GUN # A-26
SHOOTER: SW
SERIAL # 71148863
CAL :300 WIN MAG

200 RD BASIC JACK FUNCTION TEST

TLW1303
PROJECT # 241314

AMMO :		DATE : 1/13/04	ROUND LEVEL - 0
MALFUNCTIONS		MALFUNCTIONS	
LOT #			
1 Rem RS300WA Lot# R16E33523	51		
2 HTC	52		
3	53		
4	54		
5 Bolt came out (Bolt Latch Failed)	55		
6	56		
7	57		
8 Bolt came out	58		
9	59		
10 HTC	60		
11	61	Rem PRC300WC Lot# W10BB1	
12	62		
13	63		
14	64		
15	65		
16 Bolt came out	66		
17	67		
18	68		
19	69		
20	70		
21 Rem PRSC300WB Lot# T25B01	71		
22	72		
23	73		
24	74		
25	75		
26 Bolt came out HTC	76		
27	77		
28	78		
29	79		
30 HTC	80		
31	81	Rem R300W2 Lot# W27PB1	
32	82		
33	83		
34	84		
35	85		
36	86		
37	87		
38 Bolt came out HTC	88		
39	89		
40	90		
41 Rem R300W1 Lot# T05EB1	91		
42 Bolt Latch Failed HTC	92		
43	93		
44 Bolt Latch Failed HTC	94		
45	95		
46 Bolt Latch Failed HTC	96		
47	97		
48	98	Bolt Latch Failed	
49	99		
50	100		

Front of Magazine bends out makes hard to
get magazine in or out.
7 - Bolt hard to cycle over first round from magazine
13 - Bolt Latch Failed (bolt came out when cycled)

100

ET21355

GUN # A-26
SHOOTER: SW
SERIAL #
CAL :300 WIN MAG

200 RD BASIC JACK FUNCTION TEST

TLW1303
PROJECT # 241314

AMMO :		DATE : 1/15/04		ROUND LEVEL - 100	
MALFUNCTIONS		MALFUNCTIONS			
LOT #					
1	Rem PRA300WC Lot# U29IA1	51			
2		52			
3		53			
4		54			
5		55			
6	Bolt Latch Failed	56			
7		57			
8		58			
9		59			
10		60	✓		
11		61	Fed 300WGS Lot# 304J153		
12		62	Rem		
13		63			
14		64			
15		65			
16		66			
17		67			
18		68			
19		69			
20	✓	70	Bolt Latch Failed		
21	Win SHV30WM2 Lot# RNO2	71			
22	Bolt Latch Failed	72			
23		73			
24		74			
25		75			
26		76			
27		77			
28		78	Bolt Latch Failed		
29		79			
30		80	✓		
31		81	Fed P300WC Lot# 304J030		
32		82	Bolt Latch Failed		
33		83			
34		84			
35		85			
36		86			
37		87			
38		88			
39		89			
40	✓	90			
41	Win X30WM2 Lot# 4TL20	91			
42		92			
43		93			
44		94			
45		95			
46		96			
47		97			
48		98			
49		99			
50		100	✓		

300

ET21356