

Page 1 of 1

Inspection Report

2/9/2004

Part Name:	sear safety cam										
Drawing Num:	C-300502	NOTE- Dimension identifiers will be provided on the prints supplied by engineering & the CAD group.									
TLW Number:	1383										
Revision Level:		INSTRUCTIONS:									
Vendor:		1. STAMP ALL PARTS WITH AN I.D. NUMBER AND CHANGE I.D. AT TOP OF PAGE CORRESPONDINGLY.									
Requisition #:		2. TAG PARTS ONLY IF STAMPING IS NOT POSSIBLE.									
Material:		3. ENTER FEATURE DESCRIPTIONS WHEN POSSIBLE. (OPTIONAL)									
Hardness:		4. WHEN COMPLETE, RETURN ALL PARTS TO ENGINEER IN ORIGINAL SHIPPING CARTON (IF POSSIBLE) AND DRAWING WITH IDENTIFIERS.									
Metallurgist:											
Engineer:	Mike Keeney	INSPECTOR NOTES: IDENTIFIER B ALSO DONE ON LMM (JODY CARSON)									
Inspected by:	Steve Wade										
Date:	1/28/03										
Reviewed by:											
Date:											

Identifier	feature description	DIM	plus	minus	A-41	A-42	A-43	A-44	A-45	A-46	AVG	STDEV	Method
A	I.D.	0.127	0.001	0.001	0.126	0.126	0.126	0.126	0.126	0.126	0.126	0.0000	PIN
B	DISTANCE	0.1835	0.0030	0.000	0.1946	0.1941	0.1940	0.1948	0.1948	0.1844	0.194	0.0003	MV
C	DISTANCE	0.148	0.000	0.000	0.149	0.149	0.150	0.149	0.149	0.149	0.149	0.0004	MV
D	DISTANCE	0.865	0.003	0.003	0.865	0.866	0.864	0.866	0.866	0.865	0.865	0.0008	MV
E											#DIV/0!	#DIV/0!	
F											#DIV/0!	#DIV/0!	
G											#DIV/0!	#DIV/0!	
H											#DIV/0!	#DIV/0!	
I											#DIV/0!	#DIV/0!	
J											#DIV/0!	#DIV/0!	
K											#DIV/0!	#DIV/0!	
L											#DIV/0!	#DIV/0!	
M											#DIV/0!	#DIV/0!	
N											#DIV/0!	#DIV/0!	
O											#DIV/0!	#DIV/0!	
P											#DIV/0!	#DIV/0!	
Q											#DIV/0!	#DIV/0!	
R											#DIV/0!	#DIV/0!	
S											#DIV/0!	#DIV/0!	
T											#DIV/0!	#DIV/0!	
U											#DIV/0!	#DIV/0!	
V											#DIV/0!	#DIV/0!	
W											#DIV/0!	#DIV/0!	
X											#DIV/0!	#DIV/0!	
Y											#DIV/0!	#DIV/0!	
Z											#DIV/0!	#DIV/0!	

ET21401

Confidential - Subject to Protective Order
Williams v. Remington

Part Name:	saar safety cam	NOTE- Dimension identifiers will be provided on the prints supplied by engineering & the CAD group.									
Drawing Num:	C-300501										
TLW Number:	1383										
Revision Level:		INSTRUCTIONS:									
Vendor:		1. STAMP ALL PARTS WITH AN I.D. NUMBER AND CHANGE I.D. AT TOP OF PAGE CORRESPONDINGLY.									
Requisition #:		2. TAG PARTS ONLY IF STAMPING IS NOT POSSIBLE.									
Material:		3. ENTER FEATURE DESCRIPTIONS WHEN POSSIBLE. (OPTIONAL)									
Hardness:		4. WHEN COMPLETE, RETURN ALL PARTS TO ENGINEER IN ORIGINAL SHIPPING CARTON (IF POSSIBLE) AND DRAWING WITH IDENTIFIERS.									
Metallurgist:											
Engineer:	Mike Keeney	INSPECTOR NOTES:									
Inspected by:	Steve Wade										
Date:	1/28/03										
Reviewed by:											
Date:											

identifier	feature description	DIM	plus	minus	A-41	A-42	A-43	A-44	A-45	A-46	AVG	STDEV	Method
A	DISTANCE	1.226	0.002	0.002	1.225	1.223	1.224	1.227	1.225	1.224	1.225	0.0014	MV
B	DEGREE	27.00	0.50	0.50	27.02	26.96	27.08	27.08	27.17	27.07	27.063	0.0700	MV
C											#DIV/0!	#DIV/0!	
D											#DIV/0!	#DIV/0!	
E											#DIV/0!	#DIV/0!	
F											#DIV/0!	#DIV/0!	
G											#DIV/0!	#DIV/0!	
H											#DIV/0!	#DIV/0!	
I											#DIV/0!	#DIV/0!	
J											#DIV/0!	#DIV/0!	
K											#DIV/0!	#DIV/0!	
L											#DIV/0!	#DIV/0!	
M											#DIV/0!	#DIV/0!	
N											#DIV/0!	#DIV/0!	
O											#DIV/0!	#DIV/0!	
P											#DIV/0!	#DIV/0!	
Q											#DIV/0!	#DIV/0!	
R											#DIV/0!	#DIV/0!	
S											#DIV/0!	#DIV/0!	
T											#DIV/0!	#DIV/0!	
U											#DIV/0!	#DIV/0!	
V											#DIV/0!	#DIV/0!	
W											#DIV/0!	#DIV/0!	
X											#DIV/0!	#DIV/0!	
Y											#DIV/0!	#DIV/0!	
Z											#DIV/0!	#DIV/0!	

Page 1 of 1

Part Name:	trigger	NOTE- Dimension identifiers will be provided on the prints supplied by engineering & the CAD group.														
Drawing Num:	D-300463															
TLW Number:	1383															
Revision Level:		INSTRUCTIONS:														
Vendor:		1. STAMP ALL PARTS WITH AN I.D. NUMBER AND CHANGE I.D. AT TOP OF PAGE CORRESPONDINGLY.														
Requisition #:		2. TAG PARTS ONLY IF STAMPING IS NOT POSSIBLE.														
Material:		3. ENTER FEATURE DESCRIPTIONS WHEN POSSIBLE. (OPTIONAL)														
Hardness:		4. WHEN COMPLETE, RETURN ALL PARTS TO ENGINEER IN ORIGINAL SHIPPING CARTON (IF POSSIBLE) AND DRAWING WITH IDENTIFIERS.														
Metalurgist:		INSPECTOR NOTES:														
Engineer:	Mike Keeney															
Inspected by:	Steve Wade															
Date:	1/29/03															
Reviewed by:																
Date:																

identifier	feature description	DIM	plus	minus	A-41	A-42	A-43	A-44	A-45	A-46	AVG	STDEV	Method
A	I.D.	0.1259	0.0005	0.0005	.1260	.1260	.1260	.1255+	.1260	.1260	#DIV/0!	#DIV/0!	PIN
B											#DIV/0!	#DIV/0!	
C											#DIV/0!	#DIV/0!	
D											#DIV/0!	#DIV/0!	
E											#DIV/0!	#DIV/0!	
F											#DIV/0!	#DIV/0!	
G											#DIV/0!	#DIV/0!	
H											#DIV/0!	#DIV/0!	
I											#DIV/0!	#DIV/0!	
J											#DIV/0!	#DIV/0!	
K											#DIV/0!	#DIV/0!	
L											#DIV/0!	#DIV/0!	
M											#DIV/0!	#DIV/0!	
N											#DIV/0!	#DIV/0!	
O											#DIV/0!	#DIV/0!	
P											#DIV/0!	#DIV/0!	
Q											#DIV/0!	#DIV/0!	
R											#DIV/0!	#DIV/0!	
S											#DIV/0!	#DIV/0!	
T											#DIV/0!	#DIV/0!	
U											#DIV/0!	#DIV/0!	
V											#DIV/0!	#DIV/0!	
W											#DIV/0!	#DIV/0!	
X											#DIV/0!	#DIV/0!	
Y											#DIV/0!	#DIV/0!	
Z											#DIV/0!	#DIV/0!	