

Part Name:	sear safety cam	NOTE- Dimension identifiers will be provided on the prints supplied by engineering & the CAD group.											
Drawing Num:	C-300502												
TLW Number:	1383												
Revision Level:		INSTRUCTIONS:											
Vendor:		1. STAMP ALL PARTS WITH AN I.D. NUMBER AND CHANGE I.D. AT TOP OF PAGE CORRESPONDINGLY.											
Requisition #:		2. TAG PARTS ONLY IF STAMPING IS NOT POSSIBLE.											
Material:		3. ENTER FEATURE DESCRIPTIONS WHEN POSSIBLE. (OPTIONAL)											
Hardness:		4. WHEN COMPLETE, RETURN ALL PARTS TO ENGINEER IN ORIGINAL SHIPPING CARTON (IF POSSIBLE) AND DRAWING WITH IDENTIFIERS.											
Metallurgist:													
Engineer:	Mike Keeney	INSPECTOR NOTES: IDENTIFIER B ALSO DONE ON DIM (JODY CARSON)											
Inspected by:	Steve Wade												
Date:	1/28/03												
Reviewed by:													
Date:													
identifier	feature description	DIM	plus	minus	A-41	A-42	A-43	A-44	A-45	A-46	AVG	STDEV	Method
A	I.D.	0.127	0.001	0.001	0.126	0.126	0.126	0.126	0.126	0.126	0.126	0.0000	PIN
B	DISTANCE	0.1835	0.0030	0.000	0.1948	0.1941	0.1940	0.1948	0.1948	0.1944	0.194	0.0003	MV
C	DISTANCE	0.148	0.000	0.000	0.149	0.149	0.150	0.149	0.149	0.149	0.149	0.0004	MV
D	DISTANCE	0.865	0.003	0.003	0.865	0.866	0.864	0.866	0.866	0.865	0.865	0.0008	MV
E											#DIV/0!	#DIV/0!	
F											#DIV/0!	#DIV/0!	
G											#DIV/0!	#DIV/0!	
H											#DIV/0!	#DIV/0!	
I											#DIV/0!	#DIV/0!	
J											#DIV/0!	#DIV/0!	
K											#DIV/0!	#DIV/0!	
L											#DIV/0!	#DIV/0!	
M											#DIV/0!	#DIV/0!	
N											#DIV/0!	#DIV/0!	
O											#DIV/0!	#DIV/0!	
P											#DIV/0!	#DIV/0!	
Q											#DIV/0!	#DIV/0!	
R											#DIV/0!	#DIV/0!	
S											#DIV/0!	#DIV/0!	
T											#DIV/0!	#DIV/0!	
U											#DIV/0!	#DIV/0!	
V											#DIV/0!	#DIV/0!	
W											#DIV/0!	#DIV/0!	
X											#DIV/0!	#DIV/0!	
Y											#DIV/0!	#DIV/0!	
Z											#DIV/0!	#DIV/0!	