

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	
				RDS. FIRED	TOTAL RDS.
SW/JS	4/23/04	Head space	Min +.004	TLW1447A	
"	"	Head space	Bolt Type G0 won't close	"	
SW/JS	4/23/04	Proof Rd	OK Hammer bolt back	TLW1447B	1
↓	4/26/04	Head space	Min +.004	TLW1447C	
"	"	Head space	Bolt Type G0 won't close	"	
SW	4/26/04	Firing Pin Indent	.017, .017, .017 Avg .0170	TLW1447D	
↓	4/27/04	Check Loosening torque front screw	35 in/lbs	TLW1447Z	
↓	↓	Check Depth of front take down screw hole	.0140	↓	
↓	↓	Check number of turns to loosen front screw	1 3/4 Turn	↓	
↓	↓	Inspect trends & measure length	OK / 1.4905	TLW1447E	
↓	↓	Engagement	.0340, .0343, .0343 Avg .03420	TLW1447F	
↓	↓	Trigger Pull	5.366, 5.352, 5.363, 5.300, 5.360 Avg 5.348	"	
SW	4/28/04	Screw lift	.0140	TLW1447E	
SW	4/29/04	Torque Front screw	70 in/lbs	TLW1447	
SW	4/30/04	200 Rd Basic Jack Function Test		TLW1447P	200
BL	5-6-04	Clean Bolt & Bore			
PKR	5/1/04	Endurance	100 rds	TLW1447A	100
PKR	5/20/04	Investigate Hard Extract Issue, Shoot additional Rds. of Fed. & Win. Ammo & inspect cases. Case had severe scuffing approx 1/8" ahead of belt. Inspected chamber w/ bore scope small burr/lip raise @ front edge of belt counter bore.			301
		Burnished Chamber w/ proper bal received from Ilion & Took photos			
		Function Test - Test Fire same ammo as used in Jack Function w/ no problems			401
SW	5/23/04	Endurance	300 Rds	TLW1447B	300
SW	5/28/04	Clean & Inspect	Head space Min +.005	TLW1447S	701

THIS SHEET IS TO ACCOMPANY THE FIREARM AT ALL TIMES THROUGHOUT TESTING

FORMS.XLS