CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Project: 241314	TLW #: TLW1689
Date: 2 / 2.4	05
Gun Test # 4-2!	S/N 7/202765
Round Level: /23/	Inspector: <u>B. LEE</u>
Measure Headspace	
Check Takedown Screw Torque @ Disassemb	oly: Frt 40 , Center 30 , Rear 15
Sear Engagement: 1st., 1024/ 2nd., 02.55	3 rd 02 48 Ave. spec025" to.030"
Reset Sear Engagement if Required: 1st.	2 nd . 3 rd . Ave.
Trigger Pull: 1st. 5,7/3-2 3rd. 563 9 3r	Ave. <u>5.679</u> spec- 4.5 lb. to 6 lb.
Reset Trigger Pull if Required 1st.	2 nd . 3 rd . Ave.
Inspect Firecontrol Insert for any signs of cr faiture.	acking or other
Other items of	
note:	
Torque Takedown Screws @ Reassembly: SP.	EC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.
	TLW1216
•	