## CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

	Project: 241314	TLW #: TLW1689	
	Date: 2 122 105		
	Gun Test #	S/N /1202781	
	Round Level: 70/	Inspector: <u>B. L.C.C.</u>	1880 Å
<b>2</b>	Measure Headspace		<i>35</i>
	Check Takedown Screw Torque @ Disassembly: Frt 30	, Center _ 20, Rear _ /0	
<b>a</b>	Sear Engagement: 1st o2 52 2nd o2 50 3rd o2 48	Ave. 625 spec020" to.025"	
	Reset Sear Engagement if Required: 1st 2nd.	3 <sup>rd</sup> . Ave.	
<b>Q</b>	Trigger Pull: 1 <sup>st</sup> . 5.471. 2 <sup>std</sup> . 4.943. 3 <sup>rd</sup> . 5.16 2.	Ave. 5.192 spec- 4 lb. to 5.5 lb.	
	Reset Trigger Full if Required: 1st. 2nd.	3 <sup>rd</sup> Ave	
<b>2</b>	Inspect Firecontrol Insert for any signs of cracking or othe	er	
	failure.		
. <b>.</b> .	Other items of	-	
(4983) 23°	note:		
[a/	The state of the s		
	Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in	n ios, Center- 30-35 in ios, Rear- 15 in ios.	
		·	
		TLW1216	
	TD		•
Remington Confidential			

ET22112