## CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314 TLW #: T	LW1689
Date: 2 / 22 / 05	
Gun Test # <u>A-/5</u> S/N 7/3	2 02 783
Round Level: Inspector:	<u>B.LEE</u>
Measure Headspace mintide.	
Check Takedown Screw Torque @ Disassembly: Frt 30, Center	<u>∕ø.</u> , Rear _ /ð
Sear Engagement: 1st., 0238 2nd., 0237 3rd., 0295 Ave.	spec020" to.025"
Reset Scar Engagement if Required: 1st. 2nd. 3rd.	Ave
Trigger Pull: 1st. 5, 200 30t. 5.18 3rd. 5.034 Ave. 5.	<b>/</b> <u>ゲ</u> spec- 4 lb. to 5.5 lb.
Reset Trigger Pull if Required: 2nd 2nd 3rd. 3rd.	Ave
Inspect Firecontrol Insert for any signs of cracking or other	
	<u></u> ·
Other items of	
note:	
7) The second Control of December Spect For 50 in the Control of	) 25 in the Deep 15 in the
☐ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30	-35 in ibs, Rear- 15 in ibs.
	TLW1216
Remington Confidential	