## CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

## Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"	
Project: 241314	TLW #: TLW1689
Date: 2 /25 / 65	
Gun Test #	S/N 71202770
Round Level:	Inspector: B. LEE
Measure Headspace <u>win 1.00 y</u> .	
Check Takedown Screw Torque @ Disassembly: Frt_	/ひ , Center 20. , Rear /5
Sear Engagement: 1 <sup>st</sup> 024/ 2 <sup>nd</sup> 02.56 3 <sup>rd</sup> 0	<u>2√8"                                     </u>
Reset Sear Engagement if Required: 1st. 2nd.	3 <sup>rd</sup> Ave.
Trigger Pull: 1st. 4.8/3 3 4.750 3 d. 4.620	47≥8 spec- 4 lb. to 5.5 lb.
Reset Trigger Pull if Required: 1st. 2nd	3 <sup>rd</sup> . Ave.
Inspect Firecontrol Insert for any signs of cracking or	
6	
	·
ther items of	
note:	
<del></del> .	
Torque Takedown Screws @ Reassembly: SPEC- Frt-	50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.
·	TLW1216
Remington C	Confidential