

Phillip Reesor

From: Franz, Scott
Sent: 03/24/2005 09:18:01 AM
To: Lance, Kevin D.
CC: Reesor, Phillip K.; Vicars, Gerald
BCC:
Subject: Re: 710 Short Inserts

Kevin,

We've completed everything we can and so far no issues have been identified.

- * Insert to stock fit - OK
- * Firing Pin Head to Sear engagement - OK
- * Trigger position in the stock - OK
- * Non-Magnum(.30-06) Live Fire Test - OK

We're waiting for .300 WM ammunition to complete our live fire testing. This is the only thing remaining and we should finish next week assuming we get the ammo. Call if you have any questions.

By the way, we'll be shooting HB .17 HMR M/504's today for accuracy with your latest barrels. Will let you know how they shot as soon as I know.

Scott Franz

Manager Research & Technology

Remington Arms Co. Inc.

Research & Development Technology Center

315 West Ring Road

Elizabethtown, KY 42701

phone 270-769-7607

fax 270-737-9576

E-mail: scott.franz@remington.com