

**Vince Norton**

---

**From:** Ronkainen, Jim  
**Sent:** 02/18/2005 12:17:47 PM  
**To:** Norton, Vince  
**CC:**  
**BCC:**  
**Subject:** RE: M710 Parts List

Vince,

Please add one more part to your list of things to investigate - the SAP BOM doesn't include the safety pivot pin (F300932) as part of the receiver assembly insert complete (F300401) or the complete gun (27434). Are they using another part for this (300464)? I can't tell. I'm sooooo confused.....

Thanks,

Jim

---

**From:** Ronkainen, Jim  
**Sent:** Friday, February 18, 2005 11:54 AM  
**To:** Norton, Vince  
**Subject:** RE: M710 Parts List

Vince,

Can you check the sear too? SAP shows Ilion's sear 15666 being used without alteration while the P/L shows a different part numbers.

Thanks,

Jim

---

**From:** Ronkainen, Jim  
**Sent:** Friday, February 18, 2005 11:50 AM  
**To:** Norton, Vince  
**Subject:** M710 Parts List

Vince,

I'm comparing the current 710 trigger assembly (actually, receiver insert assembly complete) versus the

new SPL for Ilion (don't ask why) and I noticed that the 710 trigger in the P/L is listed as 300483 with 300482 as the blank (p. 2 of P/L), but SAP calls out 109835. Could you please check this out (and fix the P/L to reflect reality, if necessary)?

Thanks!

Jim Ronkainen

Staff Engineer

Remington Arms Co. Inc.

R&D Technical Center

315 W. Ring Road

Elizabethtown, KY 42701

(270) 769-7613 (phone)

(270) 737-9576 (fax)

[jim.ronkainen@remington.com](mailto:jim.ronkainen@remington.com)

visit us at [www.remington.com](http://www.remington.com)