

**Phillip Reesor**

---

**From:** Reesor, Phillip K.  
**Sent:** 01/26/2001 01:24:49 AM  
**To:** Franz, Scott  
**CC:** Danner, Dale; Keeney, Mike; Snedeker, Jim  
**BCC:**  
**Subject:** 710 Front Sights

During the drop test of the 710 sighted version we noticed that the front sights were prone to movement and one came out. This movement is at the dovetail joint. For the POI test we had to re-center the front sights in the dovetail, in some cases it took very little force to move the sights back to center. As for the sight that came out, it can be freely slid in and out of the dovetail by hand. Just wanted to let you know, someone may want to look into this. I believe a customer would be fairly agitated if their front sight moved or fell off.

PKR