

1. Fuzzy optics on some scopes  
2. Crosshairs rotated approx. 30 deg. on 1 scope

- \* Box bottoms - Falling off during shooting
- \* Magazine followers - Sticking in box (cause of stem low malfunction)
- \* Safety in Fire Position as received - 1 of 30
- \* "Pillar bedding" on hang tag
- \* Box removal difficult - varies
- \* Bolt Stops Loose - detent force varies
- \* Trigger position relative to trigger guard - side to side
- \* Take down screws - loosening during shooting
- \* Scope rail deformation

The topics in red are classified as potential show stoppers. These effect function and short term customer perception. We will discuss all topics in more detail at 4.00 today.