

Scott Franz

From: Franz, Scott
Sent: 11/06/2000 09:25:43 AM
To: Bristol, II Ronald H.; Golemboski, Matt R.; Diaz, Danny; Keeney, Mike
CC: Snedeker, Jim; Danner, Dale
BCC:
Subject: M/710 T & P Conference Call

Issues to discuss at the 10:00 a.m. meeting:

- * Visual Inspection Issues as identified by John Trull
 1. ISS Keys missing - (3 of 30)
 2. Stock Sink - Left side
 - * 1 of 30 unacceptable (measured .050" sink)
 - * Worst case sample identified (measured .042" sink)
 3. Hard Bolt Cycle (translation) - 1 of 30 unacceptable
 - * Improved w/cycling
 4. Bolt Stop Detent - 1 of 30 loose
- * Measurement/Function Issues
 1. Headspace - 1 of 30 won't close on E-town Min. plug.
 2. Fire Control Operation
 - * 2 of 30 guns had follow down malfunctions (A-14 & A-26)
 - * 1 of 30 inadvertently discharged (A-26)
 3. Bolt Stop Breakage - 1 of 30 during Preliminary measurements