

Scott Franz

From: Franz, Scott
Sent: 11/02/2000 08:57:22 AM
To: Golemboski, Matt R.; Zajk, Joseph J; Diaz, Danny; Keeney, Mike; Danner, Dale; Snedeker, Jim
CC:
BCC:
Subject: 10 Gun Test Summary

Attached are the summary results for the 10 gun test that was completed yesterday.

Results can be summarized as follows:(see attached file for specifics)

- * 2 Bolt Handle Braze Failures
 1. One handle failed at 107 rounds during live fire testing
 2. The second handle failed during the bolt plug abuse test
- * Trigger pulls not within Specification
- * Followers sticking in magazine boxes
- * Bolt stop detent Inconsistent
- * Bolt Closing Force High
 1. Improved over DAT (Could not measure accurately)
 2. High closing force related to extractor operation (2 guns)

In addition our "albeit" limited test shows the new bolt plug design superior. Recommend T&P samples all have the new configuration. Call if you have any questions.

Scott