

Steve Perniciaro

From: Perniciaro, Stephen
Sent: 12/08/2005 10:33:50 AM
To: Ogrodnik, Frank A.
CC:
BCC:
Subject: Re: Sear Safety Cams

Frank

Ok to run parts.

Steve p

-----Original Message-----

From: Ogrodnik, Frank A.
To: Perniciaro, Stephen; Becker, Craig; Rice, Danielle; Luke, Kyle D.
CC: Marley, Matthew M.; Orf, Robert J.; Diliberto, Joseph; Nichols, Scott; Wright, MaryAnn
Sent: Thu Dec 08 09:57:48 2005
Subject: RE: Sear Safety Cams

Steve,

Can PMPD start running our production orders?

Frank Ogrodnik 12/08/05

From: Rice, Danielle
Sent: Thursday, December 08, 2005 6:34 AM
To: Luke, Kyle D.; Perniciaro, Stephen; Becker, Craig
Cc: Ogrodnik, Frank A.; Marley, Matthew M.; Orf, Robert J.; Diliberto, Joseph
Subject: RE: Sear Safety Cams
Importance: High

I screened 50 parts this morning after H.T and there was virtually no change to the diameter of the pin hole.

Danielle

From: Luke, Kyle D.

Sent: Wednesday, December 07, 2005 4:51 PM

To: Perniciaro, Stephen

Cc: Rice, Danielle; Becker, Craig; Ogradnik, Frank A.; Marley, Matthew M.; Orf, Robert J.; Diliberto, Joseph; Murray, Joseph M.; Casanova, Robert J.

Subject: RE: Sear Safety Cams

They are in the furnace – they will be ready for Danielle 1st thing Thursday morning if they pass inspection. In the future, we should include production on parts that need to be expedited for engineering.

Kyle

From: Perniciaro, Stephen

Sent: Wednesday, December 07, 2005 3:34 PM

To: Luke, Kyle D.

Cc: Rice, Danielle; Becker, Craig; Ogradnik, Frank A.; Marley, Matthew M.; Orf, Robert J.; Diliberto, Joseph

Subject: RE: Sear Safety Cams

Kyle,

This test is holding up PmPD for their next order of sear safety cams.

Please ensure that they get H.T.'d tonight.

Thanks,

Steve P.

From: Rice, Danielle

Sent: Wednesday, December 07, 2005 2:47 PM

To: Becker, Craig

Cc: Perniciaro, Stephen

Subject: Sear Safety Cams

12/7/05

Craig

I delivered the safety cams to heat treat early this morning. I ran into some problems getting these parts to heat treat seeing no order was generated for them over in powder metals. These parts were scheduled to be run so I could inspect them this afternoon. However, when I checked on these parts after lunch they had not processed them through micro-carb. They should be processed tonight and I will follow up on them first thing in the morning. I will notify you as soon as I know anything.

Thanks

Danielle Rice

Quality Technician

Ext. 4219