

Bob Orf

From: Becker, Craig
Sent: 12/02/2005 02:11:34 PM
To: Ferreira, Louis B.; Rice, Danielle
CC: Orf, Robert J.; Diliberto, Joseph
BCC:
Subject: F15666 Sear Safety Cam

Lou,

It was discovered in the last month that the existing Sear Safety Cam F15666

is produced by PMD with oversized holes. They took corrective action,

and delivered to me a bag of 500 parts for testing. (The only paperwork that can with them was

an Engineering ticket, no Engineering order was generated) I will be traveling next week Monday – Wednesday.

I am attaching an Engineering Order form to this e-mail should you need it. I would like Danielle Rice to monitor

these parts thru normal processing. Can you attach these parts to a normal production run?

Danielle will have the parts.

Craig S. Becker

Manufacturing Engineer

Remington Arms Co. Inc

14 Hoefler Ave.

Ilion, NY 13357

(315) 895-3207

(315) 895-3670 (Fax)

E-mail: craig.becker@remington.com