## **Bob Orf**

From: Orf, Robert J.

Sent: 12/01/2005 07:02:02 AM

To: Becker, Craig

CC:

BCC:

Subject: RE: SPL Front and Rear Spacers 316L

OK thanks

Robert J. Orf

Technical Manager of Manufacturing Engineering

Remington Arms Co. Inc.

Ilion, NY 13357

Phone: 315-895-3254

Fax: 315-895-3670

Cell: 315-717-2571

From: Becker, Craig

Sent: Wednesday, November 30, 2005 12:43 PM

To: Orf, Robert J.

Subject: FW: SPL Front and Rear Spacers 318L

Bob

It sounds like the stainless spacers might not be ready until Thursday or Friday.

Craig

From: George, Ronald Mil

Sent: Wednesday, November 30, 2005 12:22 PM

To: Ogrodnik, Frank A. Parkhurst, James L. Co: Wright, Maryann; Martey, Matthew M.; Ronkainen, Jim; Doolittle, James F.; Becker, Craig Subject: RE: SPL Front and Rear Spacers 316L

When will all the samples be sintered?

----Original Message-----From: Ogrodnik, Frank A.

Sent: Wednesday, November 30, 2005 12:00 PM To: Parkhurst, James L.; George, Ronald M.

Cc: Wright, MaryAnn; Marley, Matthew M.; Ronkainen, Jim; Doolittle, James E.; Becker, Craig

Subject: SPL Front and Rear Spacers 316L

Phone conversation with Jim Ronkainen on 11/30/05 at 10:20 AM

Jim and I discussed the tolerance needed for the Stainless Steet version of the Front and Rear Spacers.

We have decided to wait until Pmpd has the dimensional data on hole size, hole spacing and hole position before Jim Ronkainen makes any tolerance changes on the current drawings. I believe we should have this information by the end of tomorrow.

Ron George,

Measure three (3) groups of samples for hole size, hole spacing and hole position.

Please let me know if this can be done by the end of tomorrow, 12/01/05.

Thanks

Frank 11/30/05

