

Customer Complaint

P.I. NA GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: NEWR #: 15003OUTSIDE WORK: TRIGGER PULL REDUCED TO
ONE POUND.DATE: 7-30-71FROM: UNITED DIST.

FIRED AMMO TYPE: _____

GALVESTON, TEXAS

& CONDITION: _____

GUN #: 6408400PROOF: R.E.P. INSP.: 74 TEST: 98CODE: LO = 2/71HEADING: O.K.GR./CAL.: 270 WIN.BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

ADJUSTING SCREW FOR TRIGGER PULL UNSEALED
AND ADJUSTMENT ALTERED.COMPLAINT: FIRING PIN ENGAGES & FIRES WHEN BOLT IS
PUSHED FORWARD.INCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT
3270COMMENTS: WHEN TRIGGER PULL WAS CORRECTED ENGAGE-
MENT OF SEAR AND TRIGGER CONNECTOR WAS .025-
MIN. IS .015 WITH TRIGGER PULL REDUCED THE
SPRING WILL NOT RETRACT THE TRIGGER CONNECTOR
CORRECTLY AND FOLLOW DOWN MAY RESULT.

1 of 1