

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 ADL

GENERAL CONDITION: NEW

R #: 07070

OUTSIDE WORK: TRIGGER ENGAGEMENT SCREW

DATE: 4-23-71

SEAL REMOVED.

FROM: LLOYD CO.

FIRED AMMO TYPE: -

LITTLE ROCK, ARK.

& CONDITION:

GUN #: 6266361

PROOF: R.I.P.-E INSP.: 73 TEST: 87

CODE: WS = 8/69

HEADING: O.K.

GA./CAL.: 22-250

BREACH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER CONNECTOR BROKEN. TRIGGER SPRING MISSING.

TRIGGER ENGAGEMENT SCREW OUT OF ADJUSTMENT.

COMPLAINT: "LEVER IN TRIGGER HOUSING BROKEN"

INCIDENT: -

COMMENTS: APPARENTLY A DEFECTIVE TRIGGER CONNECTOR WAS USED.

PLAINTIFF'S
EXHIBIT

3278