

P NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 22730
OUTSIDE WORK: NO DATE: 10-16-70
FIRED AMMO TYPE: _____ FROM: LIVONIA,
& CONDITION: _____ MICH.
PROOF: -R.E.P. INSP.: _____ TEST: _____ GUN #: 6278113
HEADING: _____ CODE: _____
BREACH OPENING: _____ GR./CAL.: 3006
RECOIL SHOULDERS: _____ CHECKED BY: C. PROSSER
CHAMBER: _____ APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR IS .005 UNDERSIZE ON 1.080
CLEARANCE) 1.083 DIMENSION (TRIGGER

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: CONNECTOR BEING TIGHT ON TRIGGER DID NOT RETRACT,
ACTION WOULD NOT COCK. AS LONG AS THE CONNECTOR
STAYED IN POSITION ON THE TRIGGER THE RIFLE WOULD
WORK O.K.



181
AL 0029843