

PROJECT# 241095

TLW 0344

200 ROUND JACK FUNCTION TEST

GUN	AMMO	ROUNDS	
A-1	REM R30065 180GR	200	NO MALFUNCTIONS
A-2	REM R30065 180GR	107	BOLT HANDLE BROKE 107 RDS
A-3	REM R30065 180GR	200	NO MALFUNCTIONS
A-4	REM R30065 180GR	200	(6) STEM LOWS, FOLLOWER STICKING. FILED FOLLOWER NO MORE MALFUNCTIONS
A-5	REM R30065 180GR	200	NO MALFUNCTIONS
A-6	REM R30065 180GR	200	NO MALFUNCTIONS
A-7	REM R30065 180GR	200	NO MALFUNCTIONS
A-8	REM R30065 180GR	200	NO MALFUNCTIONS
A-9	REM R30065 180GR	200	(6) STEM LOWS, FOLLOWER STICKING. FILED FOLLOWER NO MORE MALFUNCTIONS
A-10	REM R30065 180GR	200	NO MALFUNCTIONS

* TESTERS REPORTED THAT THE BOLT CLOSING FORCE WAS VERY HIGH WHILE ROTATING THE OPERATING HANDLE
DOWNWARD ON GUNS A-1 & A-7, THIS OCCURRED MOST OF THE TIME, BUT NOT ON EVERY CYCLE.