I recently purchased the 710 and have been reading on the Internet about it a...

Discussion Thread

Response (Chris) 12/6/2002 2:44:42 PM Dear Chris, Thank you for your inquiry. Not all 710's need to be sent in for this replacement part. If the improperly manufactured "safety Detent Spring" causes the safety mechanism to malfunction, that by itself would not cause the rifle to fire. However, although it is unlikely, if your rifle was assembled with an improperly manufactured "safety Detent Spring," then the spring may interfere with the ability of the manual safety to fully engage in the "safe" or "on" position. Moreover, the user may not be aware of the fact that the mechanism has not properly engaged. While the trigger must still be pulled to fire the rifle, this recall and spring replacement program is intended to insure that the manual safety of your rifles functions properly.

Customer (Chris Parnel]) **12**/5/2002 10:24:25 PM I recently purchased the 710 and have been reading on the Internet about it and have been quite startled to find that many people have had problems with their rifles. Are there any recalls that I need to know about or have you received many reports of problems with the rifles?

Thanks for any feedback, Chris

Subject to Protective Order - Williams v. Remington