

**IMPORTANT MESSAGE
TO OWNERS OF
REMINGTON MODEL 600
AND 660 RIFLES,
MOHAWK 600 RIFLES,
AND XP-100 PISTOLS.**

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles – **except those with a serial number starting with an “A”.**

Also included in the recall are any XP-100 pistols with a serial number below 7507984, **except those with the prefix “A” or “B” before the number.**

Remington recommends that prior to any further usage of guns included in the recall, they be inspected – and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In states except Georgia (toll free):
1-800-241-8444 – ask for operator 61
In Georgia (toll free):
1-800-282-1333 – ask for operator 61
In Canada (collect):
519-621-7271

Another important message to all gun owners.

Much has been written on firearms safety in general, and gun safeties, in particular, but we feel that a most incisive statement is contained in the NRA Hunter/Safety Handbook: “No hunter should depend wholly on the safety to prevent accidental firing. The safety is meant only to supplement proper gun handling”.

Remington Arms Company, Inc.