

I have two 700BDIs and on one, the bolt does not lock in place when the rifle...

Discussion Thread

Response (Laura) 4/24/2000 7:03:15 PM  
At 04/24/2000 04:00 PM we wrote -

Dear Mr. Lewis,  
Depending on the age of your firearm, the safety mechanism may function differently between the two rifles. The design change came about 1985. If you have a firearm that you feel may be unsafe, we recommend you send it to the factory for evaluation.

Customer (Marc Lewis) 4/22/2000 12:38:48 AM  
I have two 700BDIs and on one, the bolt does not lock in place when the rifle is in the fire "F" mode. The bolt can be retracted regardless of where the S or F switch is set. Isn't this a malfunction and I assume that it should not be fired until this is fixed. Please advise if I have a problem and what I should do to correct it.

Marc Lewis