

I recently acquired a used Remington model 721. The safety was broken on it. ...

Discussion Thread

Response (Laura) 6/21/2001 11:38:47 AM
At 06/21/2001 11:36 AM we wrote -
Dear Brian,
Thank you for your inquiry. We no longer offer parts or services for this model. We suggest contacting the following repair centers for assistance. We do not recommend any alterations on your trigger assembly.

Del Selin Gunsmith, Ltd.
2803-28th Street
Vernon, British Columbia V1T 4Z5
250-545-6413
250-545-6413 Fax

Reliable Gun & Tackle
3227 Fraser Street
Vancouver, British Columbia V5V 4B8
604-874-4710
604-874-4710 Fax

Customer (Brian Shack) 6/20/2001 4:04:58 PM
----- 06/20/2001 04:04 PM -----
I recently acquired a used Remington model 721. The safety was broken on it. It was broken right behind the trigger assembly.
I replaced the safety but the new one is very hard to use. When you try and use the safety it is almost impossible to pull it back. I have looked and cannot see where it is binding with the amount of force that it takes to put the safety on, I would expect that I would see some bluing on the new safety being rubbed off, but there is no sign of this. I have checked and there are no parts that are seized up. I would like any ideas of what to look for to try and correct this problem.
Also I would like to know about the 2 set screws on the trigger assembly. Is there a factory setting for these screws. I know one is the sear engagement and the other is trigger pull. How do I check to see if these are set correctly. I was told that someone might have adjusted these screws before I acquired this firearm. I have not fired it yet.