

The stainless rear action screw has always been about 1/8th" too short. I ordered...

#### Discussion Thread

##### Response (Laura)

Dear Mr. Allen, Thank you for your inquiry. We have a Safety Modification Program on certain model bolt action rifles. This is a voluntary program, it is not a recall. This is designed to remind people of the existence of the bolt-lock feature and to offer customers the opportunity to modernize their products.

You can read more information regarding our firearms and our Safety Modification program through the front page of our website or the link below:

[http://www.remington.com/safety\\_modification\\_program/remington\\_safety.htm](http://www.remington.com/safety_modification_program/remington_safety.htm)

The safe use and performance of your firearm depends on correct assembly and routine maintenance, as well as adherence to the "10 Commandments of Firearm Safety." <http://www.remington.com/support/10comm.htm> It is critical that you familiarize yourself with the information in both the owners manual and safety booklet. Whether you are a veteran shooter with a collection of Remington firearms, or a first time shooter, take the time to review this important literature and be certain that you are practicing firearm safety!

If you have any questions, please feel free to contact us at 1-800-243-9700 or 1-877-387-6691.

##### Customer (peter parys)

The stainless rear action screw has always been about 1/8th" too short. I ordered a new one thinking the original screw was short but it was also short, therefore it must be the stock fit or thickness causing the problem. I have used this way for years, but am now going on a trip and want to take no chances of it coming loose or stripping. Could you possibly send me a longer screw and a new owners manual for this rifle? Thanks, Peter Parys