

I recently purchased the above rifle in a 22-250 chambering in near new condi...

Discussion Thread

Response (Laura)

3/28/2002 11:18:27 AM

Dear Mr. Nelson,

Thank you for your inquiry. According to the information provided, this firearm was manufactured in or around 1966. We currently have a Safety Modification Program on certain model bolt action rifles. This is designed to remind people of the existence of the bolt-lock feature and to offer customers the opportunity to modernize their products.

You can read more information regarding our firearms and our Safety Modification program through the front page of our website or the link below:

http://www.remington.com/safety_modification_program/remington_safety.htm

As with any used firearm, we would strongly recommend you have the firearm serviced and evaluated by a competent gunsmith for function and safety. We feel it is imperative you know the exact condition of your firearm prior to shooting. Please also read our "Guide to Buying a Used Gun" found through the link below:

<http://www.remington.com/magazine/preview/rc007007.asp>

If you are not aware of a gunsmith in your area, please feel free to contact one of our RARC's found in the Support/Repair section of our website or the following link:

<http://www.remington.com/repairsvc/modelselection.asp>

If you will complete the form located in the What's New/Reading Room section of our website, we will forward to you a copy of the original owner's manual.

<http://www.remington.com/whatsnew/readroom.htm>

You can also find owner's manuals for some of our current models on-line in our Reading Room in the "What's New" Section.

Customer (Rick Nelson)

3/27/2002 8:14:04 AM

I recently purchased the above rifle in a 22-250 chambering in near new condition. A few questions, as I am quite interested in knowing more about this firearm. It seems to be quite an early model. It has the square safety lever knob and the short bolt plug. I was under the impression that the first year (1962) production rifles had these two features. However the 22-250 became a factory cartridge in 1965. Can you shed some light on this for me please?