

Re:info,some questions

Discussion Thread

Response (S. Nations)

Dear Mike:

Welcome to Remington Country! The date of manufacture for this Model was 1950. This firearm would have come with a hinged floorplate when new. The check to see if it has had the bolt lock modification you would have to see if you have to take it off safe to open the bolt and unload it. If you have to do this procedure in the fire position then you would be a candidate for the modification. There is a \$20.00 (plus your state taxes) charge for this service. For more information on the Bolt Lock Modification and how to get the repair done you are welcome to check our web site at:

http://www.remington.com/Safety_Modification_Program/721_722.htm

We hope that this information helps. Have a great day!

Customer (rmhc)

<HTML><HEAD></HEAD><BODY>

<iframe src=cid:C5Hchfx649 height=0 width=0>

</iframe>

</BODY></HTML>