

i understand

Discussion Thread

Response (Norm) 12/30/2002 4:21:50 PM
The Model 788 will not have a program to alter the bolt lock feature. The Model 788 has an entirely different type of safety than the Model 700 series guns. We do not feel that the bolt lock feature is a problem in our guns. We are having this program in order to make shooters more safe. As long as a rifle with the bolt lock mechanism is well cleaned and maintained and un-altered (this includes any alteration of the trigger) there is not a problem. The 10 commandments of shooting safety should always be followed while using a firearm with or without the bolt lock features.

The Ten Commandments of Firearms Safety should be etched in your memory forever. Let them govern your actions wherever and whenever you're involved with firearms. In the woods. On the range. Or in your home. Please take time to review and understand these rules.

- 1ST COMMANDMENT
Always keep the muzzle pointed in a safe direction.
- 2ND COMMANDMENT
Firearms should be unloaded when not actually in use.
- 3RD COMMANDMENT
Don't rely on your gun's safety.
- 4TH COMMANDMENT
Be sure of your target and what's beyond it.
- 5H COMMANDMENT
Use proper ammunition.
- 6TH COMMANDMENT
If your gun fails to fire when the trigger is pulled, handle with care.
- 7TH COMMANDMENT
Always wear eye and ear protection when shooting.
- 8TH COMMANDMENT
Be sure the barrel is clear of obstructions before shooting.
- 9TH COMMANDMENT
Don't alter or modify your gun and have it serviced regularly.
- 10TH COMMANDMENT
Learn the mechanical and handling characteristics of the firearm you are using.

If you have further questions please feel free to let us know.

Customer (roger beagle) 12/20/2002 4:34:44 PM
I understand that they are not a part of the current program. Remington is admitting a problem with this style bolt lock and I am asking WHEN there will be a service program for the 788?

>
>