

There is a trigger problem with the 600's. Is this one of them with the probl...

Discussion Thread

Response (Chris)  
Dear Mr. Kennedy,

3/21/2003 9:47:03 AM

Thank you for contacting Remington Country. Your Model 600 was produced in 1975 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/ModelSelection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/safety\\_modification\\_program/remington\\_safety.htm](http://www.remington.com/safety_modification_program/remington_safety.htm)

Customer (Neil Kennedy)

3/18/2003 9:49:52 AM

There is a trigger problem with the 600's. Is this one of them with the problem?