

I inherited this rifle from my Dad's estate. I read on the web there might be...

Discussion Thread

Response (Debbie)
Dear Terry;

7/1/2003 10:10:28 AM

Welcome to Remington Country!

According to the information you have provided us your Sportsman 78 with serial number B6646563 was manufactured in 1986.

Remington Sportsman 78, Model Seven and 710 bolt-action rifles are not included in the safety modification program. These rifles have been manufactured since 1982 and do not have a bolt lock mechanism. As a result these rifles may be loaded or unloaded with the safety in the "S" or "On Safe" position.

Nevertheless, as with any firearm, special care must be taken during the loading and unloading process. Always keep the muzzle pointed in a safe direction. Always unload your rifle when not actually in use. Keep the safety in the "S" or "On Safe" position at all times until you are ready to shoot. Every firearm should be unloaded as soon as you are finished shooting - before taking it into your car, camp or house. Remington wants you to enjoy the shooting sports safely!

Should you desire service on any of your Remington firearms please feel free to call us on our toll free service line (800) 243.9700 or visit the Remington Authorized Repair Center nearest you.

We hope you find this information useful and if we can be of any further assistance please call us at 1-800-243-9700 Mon-Fri 9am-5pm EST.

Thank you for visiting Remington Country and have a nice day.

Customer (Terry Mott)

6/30/2003 2:58:12 PM

I inherited this rifle from my Dad's estate. I read on the web there might be a trigger safety issue and would like to know if the above serial number is involved. If so where do I get it fixed?