Rifle History

Discussion Thread

Response (Norm) Dear Kurt:

8/22/2003 9:37:52 AM

Thank you for visiting Remington Country. The Remington Model 721 was produced from 1948 until 1961 in long action calibers only. The Model 722 was virtually an identical gun except it was charbered for short action calibers only and was in production at the same time. Both of these guns were replaced by the Remington Model 700 in 1963. According to the information that you provided, your Remington Model 722 was produced in or around 1952. These guns originally sold for around \$79.95 and did not come with any sling swivels installed from the factory.

mechanism. These models were discontinued in 1961. If you participate in the Safety Modification Program, your firearm will be cleaned and inspected for proper functioning, by a qualified gunsmith. Once the condition of your firearm has been assessed, you will be notified of one of the following: All Remington Model 721 or 722 rifles were manufactured with a bolt-lock

Your rifle's trigger assembly is otherwise in good operating condition and the gunsmith will proceed to physically remove the bolt-lock feature so that your rifle can be loaded and unloaded while the safety remains in the "S" or "On Safe" position; or

Your rifle's trigger assembly is found to be in an unsatisfactory or potentially unsafe operating condition because of any number of factors, including wear, alteration or maintenance. The entire trigger assembly will be replaced with a new factory trigger assembly, which does not incompare a balt lock machines. incorporate a bolt-lock mechanism.

In either case, the total cost to you is \$20, plus tax. You will also receive a rebate coupon good for up to \$20 toward the purchase of any Remington safety product, including gun locks, hearing and eye protection, and gun safes.

How to participate in the safety Modification Program:

1. Complete the General Repair Form; and 2. Send or deliver your firearm and the completed repair form to either;

a. A Remington Authorized Repair Center; or b. Ship your firearm to the Remington factory at:

Remington Arms Company, Inc. Ilion Firearms Plant Attention: BL Safety Program 14 Hoefler Avenue Ilion, NY 13357


Remington will bill or arrange for payment once your firearm is received and evaluated

CAUTION: It is your responsibility to comply with all laws and regulations regarding transportation or shipping of your firearm. Absolutely no ammunition should be packaged with the firearm either in the firearm itself or in its shipping container. The firearm should be transported only in a completely unloaded condition.

Customer	(Kurt Waldhauser)	
	dia.	

8/21/2003 8:27:24 PM

Subject to Protective Order - Williams v. Remington



MAE00006297