

mohawk 600 safety

Discussion Thread

Response (Chris)
Dear Mr. Cannon,

10/14/2003 11:17:52 AM

Thank you for contacting Remington Country. Your Model 600 with a serial number begining with a was produced around 1977. The 7 digit serial number was produced in 1975. Both should be inspected for a trigger recall if they do not have a "V" stamped on the trigger. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/ModelSelection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (walter cannon)
SN A6390908 , and SN6861003.

10/7/2003 5:22:56 PM