

remington model 600

Discussion Thread

Response (Chris)

2/24/2004 2:38:56 PM

Dear Mr. Tumolo,

Thank you for contacting Remington Country. Your Model 600 was produced in 1966 and should be inspected for a trigger recall. If it has already been inspected for the trigger recall, it would have a "V" stamped on the trigger.

We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state. Many can also provide refinishing.

<http://www.remington.com/repairsvc/ModelSelection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

To view the history on this model and the Mohawk 600, go to:

Customer (eugene tumolo)

2/20/2004 8:03:06 PM

I recently purchased a used Remington model 600 .308 cal., serial number 81676. could you tell me when it was manufactured. I recall that the model 600 was manufactured sometime during the late 60s or 70s,, and i thought another model called the "mohawk" was also made during these years. Am i correct? I also wish to know the years when these models were manufactured, and if Remington plans on ever re-introducing them in their line in the future. My sons and i are true fans of Remington products, and each of us own several Remington rifles. When i looked over the Remington web site, and requested information on service, particularly having a few of our Remington rifles and shotguns re-blued and checked over, we were given the names of three private gunsmiths. Are we corect in assuming these shops preform all service on Remington guns. I would be most appreciative of a response to my questions. thanks for your anticipated assistance.