

700 BDL Repair

Discussion Thread

Response (Chris)
Dear Mike,

9/2/2004 4:47:25 PM

We apologize for the inconvenience. We do not show any previous emails from this email address.

We will need the serial number of the rifle to check for any recall on this rifle.

Models produced before 1982 may have been originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Mike Patty)
To whom it may concern:

8/31/2004 9:12:12 PM

I sent a message 2 weeks ago with no response. I understand that Remington has a recall on rifles regarding a problem with the safety being faulty & causing an accidental discharge.

I have a 30-06, 270 & 280 and would like to know if there is a no-charge repair. I would like to find out if there's a local (Tulsa, OK) repair center.

Please advise.

Thanks,

Mike