

Model 600

Discussion Thread

Response (Chris)

1/19/2005 11:32:52 AM

Dear Mr. Rathgeber,

Thank you for your patience. Your Model 600 was produced around 1965 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Remington does not offer repair or reconditioning on discontinued models, however the following Remington Repair Center specializes in reconditioning and may be able to offer rebarreling. They can also check the trigger regarding the recall.

Craig Colabaugh Gunsmith, Inc.
R.D. 4 Box 4168- Gumm Street
Stroudsburg, PA 18360
Phone: 570-992-4499

Customer (Jack Rathgeber)
Greetings:

1/12/2005 12:33:41 PM

I found the recall notice on your website. My rifle is a 6 mm. I will be sending the rifle for that work. We took the open sights off shortly after we got it (new) and mounted a scope. Over the years, the detant thing holding the front sling swivel failed and the rib was broken when the rifle was dropped. I have been unable to find a replacement.

I don't really want the rib and want the pokey things that hold it even less. Can that entire unit be removed?

What is the feasibility of rebarreling to 260 Remington - barrel length not more than 20 inches?

Do you have a synthetic stock for this rifle?

This is a resubmission of a previous question since no answer has been received.

Thanks Jack