

recall

Discussion Thread

Response (Chris)  
Dear Mr. Black,

4/4/2005 2:28:23 PM

By the serial number, your Model 600 was produced around 1964 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Robert Black)

3/23/2005 11:01:26 AM

its serial # is 3599 in a 222 , not a 223 like I first said thanx >

>