

Remington Model 660 - 308 cal.

Discussion Thread

Response (Chris)
Dear Mr. Noland,

10/11/2005 4:25:41 PM

Thank you for contacting Remington Country. Your Model 660 was produced in 1967 and should be inspected for a trigger recall if you do not see a "v" stamped on the trigger. The "v" signifies we have already inspected it for the trigger recall.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Dan Noland)

10/5/2005 3:02:36 PM

Your records should show that many years ago I was the original purchaser of a Model 660 Rifle in .308 cal, SN 100698. I was recently told that this gun was the subject of a recall many years ago and that I should have been advised. The rifle has been in storage for some time and I would like to put it back into use but do not want to put myself or others in danger if this information is correct. Please advise.