

Remington 600 discharge with bolt close

Discussion Thread

Response (Jule)

1/16/2006 11:13:18 AM

Dear Eric,

Welcome to Remington Country! Thank you for letting us know about this issue, you still have an opportunity to take part in the Safety Modification Program if you would like. You can find this information on the home page of our web site.

Customer (Eric Berg)

1/11/2006 1:39:18 PM

My Remington 600 Mohawk with the gold colored trigger and plastic trigger guard/base plate discharged when I closed the bolt. I don't know if the bolt was completely closed when this occurred or not. Examination of bolt lugs indicates no shearing or damage. The weapon has not gone through the bolt/trigger recall.

I don't want anything from Remington. I do want you that this happened.