

Danny Evans

From: Shoemaker, Christopher D.
Sent: 11/11/2003 07:21:21 AM
To: Evans, Danny
CC:
BCC:
Subject: RE: RAMAC 4687 673 Guide

Thanks Danny, I will have gun examined when it arrives. I have seen this condition on one other firearm. The trigger did not protrude outside the guard but it came pretty close. In that case it looked as though the fire control assembly had been struck, prior to the stock being assembled. I'll let you know what we find out after we examine the firearm.

-----Original Message-----

From: Evans, Danny
Sent: Monday, November 10, 2003 3:14 PM
To: Nagle, Thomas J.; Longo, Robert W.
Cc: Shoemaker, Christopher D.; Trull, John; Loschin, John
Subject: RAMAC 4687 673 Guide

Chris,
One of the CSR's received a call this AM from a Lynn's Leisure Times (dealer) in Davenport, NY...Had a 673 guide rifle in 350 Rem Mag stated that the trigger was so far off center that it was nearly outside of the trigger guard & created a liability issue. He was going to return gun back to the factory....apparently lives relatively close. He had also spoken to Jerry's (dist) from whom he had purchased. They had same issue.

I contacted Jerry's & spoke with Richard (head of purchasing) he did have (1) gun that he had opened & inspected & found trigger off center...did not protrude beyond trigger guard, but trigger was parallel with one side of trigger guard.

I have issued an RGA for this gun to be returned to Ilion.....Attn: Bob Longo RGA #60038346...

He will wait till this gun is received at the factory & we have had the opportunity to inspect the TPA and advise on how to proceed.

Sent this one directly to factory & att: Longo so that hopefully it will find its way to Bob even if during shut down

Daniel C. Evans
Service Operations Manager
Remington Arms Company, Inc.
870 Remington Drive
P.O. Box 700
Madison, North Carolina 27025-0700
Phone: (336)543-8701
Fax: (336)543-7899
E-mail: Danny.Evans@Remington.com
Visit Remington Country at www.Remington.com