

JOHN LOSCHIN

From: Atkins, Denise
Sent: 07/17/2002 09:27:12 AM
To: Egland, Raymond T.
CC: Loschin, John
BCC:
Subject: repairs/ 49032 and 49039

Good Morning. On the above repairs, both for Mr. Combs, why do we need the balance of arms for the Model 660 (repair 49032) as stated in the repair notes? And why is there a charge of \$96.99 on repair 49039 for the 722 – it shows just a new trigger assembly, which is part of the safety modification program. Give me a call or e-mail when you can. Thanks Ray.

Denise G. Atkins

Remington Arms Company

Consumer Service

Telephone: 336-548-8799

Fax: 336-548-7801

denise.atkins@remington.com